

NO. Agenda : 203/10/2016
 Perihal : Hasil Pemeriksaan Air Bakteriologis
 Permenkes 416/MENKES/PER/IX/1990 &
 Permenkes No 492/MENKES/PER/IV/2010



DINAS KESEHATAN KABUPATEN GORONTALO
UPFD INSTALASI LABORATORIUM KUALITAS AIR



Jln. Adam Poliyumu

Sampel Berasal dari : Air Sungai
 Petugas Pengambil : Masri Jasni. CS
 Wilayah Kerja : Prov. Gorontalo

Kepada Yth,
DR. MARIKE MAHMUD
 Di-
 Tempat

PEMERIKSAAN BAKTERIOLOGIS

NO	Sumber Sampel	Diambil tgl. Diperiksa tgl	Pemeriksaan Coliform			Pemeriksaan E. Coli			MPN / 100 ml		Ph	Cl2 mg/1	PERTIMBA
			10 ml	1 ml	0,1 ml	10 ml	1 ml	0,1 ml	A.	B.			
1	Bendungan Alo Pohu (AL 1) (N 0° 37' 20,74") (E 122° 53' 26,85")	09 Oktober 2016	5 / 5	5 / 5	5 / 5	3	0	0	2400	9	7,7		
2	Sungai Alo (AL 2) (N 0° 38' 52,44") (E 122° 52' 4,03")	09 Oktober 2016	5 / 5	5 / 5	5 / 5	2	0	0	2400	5	7,9		
3	Sungai Alo (AL 3) (N 0° 39' 26,07") (E 122° 51' 20,36")	09 Oktober 2016	5 / 5	5 / 5	5 / 5	1	0	0	2400	2	7,7		
4	Sungai Alo (AL 4) (N 0° 42' 4,30") (E 122° 51' 6,29")	09 Oktober 2016	5 / 5	5 / 5	5 / 5	1	0	0	2400	2	7,8		
5	Sungai Alo (AL 5) (N 0° 44' 43,6") (E 122° 50' 57,75")	09 Oktober 2016	5 / 5	5 / 5	5 / 5	0	0	0	2400	0	7,7		
6	Sungai Toidito (AL 6) (N 0° 41' 13,83") (E 122° 49' 15,00")	09 Oktober 2016	5 / 5	5 / 5	5 / 5	0	0	0	2400	0	7,8		
7	Sungai Molalahu (AL 7) (N 0° 40' 38,65") (E 122° 47' 55,91")	09 Oktober 2016	5 / 5	5 / 5	5 / 5	0	0	0	2400	0	7,8		
8	Sungai Molamahu (AL 8) (N 0° 40' 34,97") (E 122° 47' 35,00")	09 Oktober 2016	5 / 5	5 / 5	5 / 5	0	0	0	2400	0	7,7		

Mengeluarkan,
 Kepala Unit Pelaksana Teknis Dinas
 Instalasi Laboratorium Kualitas Air
 Kabupaten Gorontalo
MUHSYARIF HUDA, S.TM, M.MKes
 NIP. 196305130198712 1 002

Telaga Biru, 20 Oktober 2016
 Tehnisi Laboratorium
MASRI JASNI
 NIP. 19820807 200604 1 011